DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/24/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY COMPLETED	
			A. BUILDING 01		G 01		
		155377	B. WING			R 07/18/2012	
NAME OF PROVIDER OR SUPPLIER SEYMOUR CROSSING				STREET ADDRESS, CITY, STATE, ZIP CODE 707 S JACKSON PARK DR SEYMOUR, IN 47274			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	DRRECTIVE ACTION SHOULD BE FERENCED TO THE APPROPRIATE	
{K 000}			{K 0)00}	}		
	INITIAL COMMENTS A Life Safety Code and Environmental Preoccupancy Survey for the relocation of beds for Room 102 from 0 beds to 1 bed, Room 110 from 1 bed to 2 beds, Room 117 from 0 beds to 1 bed, Room 819 from 1 bed to 2 beds, Room 820 from 1 bed to 2 beds, Room 820 from 1 bed to 2 beds, Room 915 from 1 bed to 2 beds, Room 915 from 1 bed to 2 beds, and Room 918 from 1 bed to 2 beds; a Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 05/31/12, and a Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 07/18/12 Facility Number: 000272 Provider Number: 155377 AIM Number: 100274710 Surveyor: Mark Bugni, Life Safety Code Specialist At this Life Safety Code and Environmental Preoccupancy, PSR, and Quality Assurance Walk-thru survey; Seymour Crossing was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies, and 410 IAC 16.2-3.1-19, Environment and Physical Standards						
LABORATORY	DIDECTOR'S OR PROVINCER	SUPPLIER REPRESENTATIVE'S SIGNATURE			TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/24/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
		155377	B. WING			R 07/18/2012	
NAME OF PROVIDER OR SUPPLIER SEYMOUR CROSSING				70	EET ADDRESS, CITY, STATE, ZIP CODE 07 S JACKSON PARK DR EYMOUR, IN 47274	<u> </u>	5/2012
(X4) ID PREFIX TAG		ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	CTION SHOULD BE O THE APPROPRIATE		
{K 000}	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Continued From page 1 This one story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors, and battery operated smoke detection in all resident sleeping rooms. The facility has a capacity of 100 and had a census of 75 at the time of this visit. The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage. All areas where residents have customary access were sprinklered and all areas providing facility services were sprinklered. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 07/23/12.		{K (000}			